
## Appendix 1



Sectional Model Test As Built Section with Means Prevention Barrier and Horizontal Mesh		Figure No. 3-2	RW
Full Icing Condition Burgoyne Bridge - St. Catharines, Ontario	Project #1901852	May 31, 2019	